

Correction to "Material characterization for magnetically confined fusion: Surface analysis and method development"

- Page 18: Concerning the magnetic field geometry in a divertor tokamak, it is stated that the field strength is zero at the x-point. This is incorrect. While the poloidal magnetic field component is indeed zero, the toroidal component is not.